

Incident Event Log		Version Name: Overall	
Incident Name: 2nd 80's Fire			
04/02/2019 23:00	Tank Farm Operations - PAR Report - 47 ITC & 81 Contractors		
04/02/2019 23:30	Tank Farm Operations - Foam Count Update: 239 Totes and 72 Drums.		
04/03/2019 00:00	Air Monitoring Detection Report: Benzene Div B - 2 readings - 0.175ppm & 0.260ppm Div E - 22 readings ranging from 0.010ppm-3.950ppm Industrial Area - 1 reading @ 0.275ppm		
04/03/2019 00:30	Tank Farm Operations - Transfer operations to Tank 100-28 started utilizing the frac tank system .		
04/03/2019 01:00	Tank Farm Operations - Tank Volume Update: per phone call with ops. Tank 80-33 has current volume of 35,736bbls, Tank 80-34 has current volume of 59,677bbls with a flow of 536/hr, Tank 50-2 has a current volume of 38,559bbls with a flow of 473/hr Tank 100-28 has a current volume of 15,207bbls with a flow of 2,145/hr, Tank 100-15 has a current volume of 52,207bbls with a flow of 2,154/hr, Tank 100-31 has a current volume of 59,638bbls with a flow of 1,621/hr.		
04/03/2019 01:00	Air Monitoring Detection Report: Benzene Div B - 4 readings ranging from 0.080ppm & 0.250ppm Div C - 3 readings ranging from 0.025ppm-0.075ppm Div E - 30 readings ranging from 0.080ppm-2.075ppm Industrial Area - 1 reading @ 0.325ppm		
04/03/2019 02:20	Tank Farm Operations - Tank 100-28 transfer to Tank 100-15 is complete.		
04/03/2019 03:00	Tank Farm Operations - Foaming application started for the tank farm containment area.		
04/03/2019 03:00	Tank Farm Operations - Tank Volume Update: per phone call with ops. Tank Farm Operations - Tank Volume Update: per phone call with ops. Tank 80-34 has current volume of 59,221bbls with a flow of 228/hr, Tank 50-2 has a current volume of 39,505bbls with a flow of 473/hr Tank 100-28 has a current volume of 11,108bbls with a flow of 2,138/hr, Tank 100-15 has a current volume of 56,640bbls with a flow of 2,253/hr, Tank 100-31 has a current volume of 60,034bbls with a flow of 792/hr.		
04/03/2019 03:40	Tank Farm Operations - Foaming application complete for the tank farm containment area.		
Incident Event Log		Prepared By IAP Support, Updated 4/3/2019 3:47:07 AM UTC -6:00 PP	
INCIDENT ACTION PLAN SOFTWARE™	Printed 04/03/2019 03:47 UTC -6:00	Page 36 of 36	© TRG